


# VM704P

## Welding plate for VV600 and VV700 series of seismic detectors

### Steel plate

---

Use the VM704P welding mounting plate when drilling in the protected steel surface is impractical or impossible when you want to mount a seismic detector.



# VM704P

## Welding plate for VV600 and VV700 series of seismic detectors

### Technical specifications

---

#### General

Accessory group	Seismic sensors
Type	Mounting

